



Intensive Deep Cleaner RM 750, **NTA-free**

Powerful deep cleaner effectively removes the most stubborn stains, such as oil, grease, soot, blood and proteins. Low foam production. Particularly suited for floor cleaning by machine and for processing with hard surface cleaners.











Properties

- Intensive basic cleaner for use with high-pressure and floor cleaning units
- For thorough cleaning of heavily soiled industrial floor coverings
- Dissolves heavy oil, grease and mineral stains
- Rapidly effective
- Low-foam formulation
- Extremely economical
- Tensides biodegradable in accordance with EEC 648/2004
- Quick oil and water separation in the oil separator (easily separable=asf)
- NTA-free

Application areas:

Agriculture: Transport and machines

Car dealership and garage: Car/engine wash Car dealership and garage: Parts cleaning

Building Industry: Transport and machines

Building cleaning: Floor cleaning Industry: Surface degreasing

Usage options


- High-pressure cleaner
- Scrubber driers
- manual

Container sizes	Part number
10	6.295-539.0
200 I	6.295-540.0













Application:

High-pressure cleaner

- Apply primary mixture with fresh water.
- Set the dosage and temperature on the device
- 1-80°C processing temperature.
- Clean object.
- Rinse surface well with clear water.

Scrubber-driers - deep cleaning

- Combine the product with the appropriate dosage and fresh water.
- Allow to soak.
- Contact time 10-15 minutes, depending on the degree of soiling.
- Wet object completely with the product.
- Clean the surface in overlapping sections.
- Neutralise with clear water.

manua

- Combine the product with the appropriate dosage and fresh water.
- Allow to soak.
- Contact time 10-15 minutes, depending on the degree of soiling.
- Wet object completely with the product.
- Incorporate the cleaning fluid.
- Neutralise with clear water.

Instructions for use:

- Test on an inconspicuous part for material compatibility.
- Do not let the cleaning solution dry out.

Warnings and safety recommendations according to EC Directives:

- Danger
- H290 May be corrosive to metals
- H314 Causes severe skin burns and eye damage
- P280 Wear protective gloves/protective clothing/eye protection/face protection.
- P305 + P351 + P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
- P310 Immediately call a POISON CENTER/doctor.
- P303 + P361 + P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].
- P405 Store locked up.
- P501a Dispose of contents/container in accordance with local/regional/ national/international regulations.

Further information:

■ Material Safety Data Sheet (MSDS)

Dosage and yield:

Contents:	Cleaning method:	Primary mixture:	Dosage:	Soiling:	Yield:
1000 ml	High-pressure cleaner	1+3	1-5 %	heavy	270 m²
1000 ml	Scrubber driers – Stripping		10-50 %	heavy	110 m²
1000 ml	Scrubber-driers - deep cleaning		5-50 %	heavy	370 m²
1000 ml	Scrubber driers - maintenance cleaning		1-5 %	light-medium	3300 m²
1000 ml	manual		5-50 %	heavy	120 m²

Please contact us for more information:

Alfred Kärcher SE & Co. KG

Alfred-Kärcher Straße 28-40 71364 Winnenden

Phone +49(0)7195-14-0 Fax +49(0)7195-14-2212

www.kaercher.com